

**Cultural Resource Re-evaluation Form**  
(page 1 of 2)

Rev. 9/98

1. Resource Number: 5JA784 2. Temp. Resource Number: \_\_\_\_\_3. Attachments  
(check as many as apply)

- ☒ Photographs  
☐ Site sketch map  
☒ U.S.G.S. map photocopy  
☐ Other \_\_\_\_\_  
☐ Other \_\_\_\_\_

4. Official determination  
(OAHP USE ONLY)

- ☐ Determined Eligible  
☐ Determined Not Eligible  
☐ Need Data  
☐ Nominated  
☐ Listed  
☐ Contributing to N.R. District  
☐ Not Contributing to N.R. Dist

5. Resource Name: Allard Ranch

6. Purpose of this current site visit (check as many as apply)

- ☐ Site is within a current project area  
☐ Resurvey  
☒ Update of previous site form(s)  
☐ Surface collection  
☐ Testing to determine eligibility  
☐ Excavation  
☐ Other \_\_\_\_\_

Describe Early 20<sup>th</sup> century ranch complex located in North Park; Arapaho National Wildlife Refuge  
Headquarters.

7. Previous Recordings: The Allard Ranch was recorded in 1991 by the U.S. Fish and Wildlife Service. At that  
time the Colorado SHPO determined that the complex was not eligible, but that the barn was potentially eligible.  
During subsequent consultation in December 2002, your office requested a re-evaluation of the structure.

8. Changes or Additions to Previous Descriptions: None

Resource Number: 5JA784

Temporary Resource Number: \_\_\_\_\_

**Cultural Resource Reevaluation Form**

(page 2 of 2)


9. Changes in Condition: When the structure was recorded in 1991, it was used by the Refuge as a barn and storage. The Refuge still uses and maintains the barn. There are no noticeable changes.
10. Changes to Location or Size Information: None
11. Changes in Ownership: None
12. Other Changes, Additions, or Observations \_\_\_\_\_
13. National Register Eligibility Assessment:  
Eligible \_\_\_\_ Not eligible X Need data \_\_\_\_\_  
Explain: The barn does not possess characteristics that make it eligible for nomination to the National Register. It is not associated with any significant events or individuals and lacks those qualities that would make it architecturally significant. It is typical of barns throughout the west in that it was used to house livestock during its life as part of an operating ranch.
14. Management Recommendations: The current level of use and maintenance is recommended.
15. Photograph Types and Numbers: Black-and-white photographs were taken on July 10, 1991 and color photographs on June 5, 2003. The photographs and negatives are on file in the U.S. Fish and Wildlife Service Regional Office.
16. Artifact and Field Documentation Storage Location: \_\_\_\_\_
17. Report Title: \_\_\_\_\_
18. Recorder(s): Rhoda O. Lewis 19. Date(s): 06/05/03 07/10/91
20. Recorder Affiliation: U.S. Fish and Wildlife Service

Colorado Historical Society, Office of Archaeology & Historic Preservation  
1300 Broadway, Denver, CO 80203  
303-866-3395



**Figure 1: 1991 and 2003 photos of the east and south walls of the Allard Barn.**





**Figure 2: Topographic map showing the location of the Allard Ranch, T8N, R79W, Section 32**